





F16.11














FIG. 4






F16.8

90		,91		/9 ²	-	93	,) &	95	96	5 7
:	mana/										
Name	Туре			g_Part	New_Part Type Index		SACS	SACS Operation	Assem. Tree	Assembly (Diseasem-	
AGAINST_FIT	NA.	NA	NA	NA	0000	0000	0023	NA	NA	A/D0023	
SCREW_FIT	NA	NA	NA.	NA	0000	9001	0023	NA.	NA	A/D0023	
Simple Part Mating Operations	NA	NA	NA	NA	0000			NA NA	NA	A/D	
SPH_AGAINST	NA	NA	NA	NA	0000	0018	2300	NA	NA	A/D2300	
P_0	NA	NA	NA	NA	0001	0000	NA	NA	NA		
P_1	NA	NA	NA	NA	0001	0001	NA	NA	NA		
P_N	NA	NA	NA	NA	0001	N	NA	NA	NA		
	NA	NA	NA	NA				NA	NA		
H_G_0	NA	NA	NA	NA	0002	0000	3011	NA	NA	A/D3011	
H_G_N	NA	NA	NA	NA	0002	N		NA	NA	A/D	
H_0	NA	NA	NA	NA	0003	0000	3010	NA	NA	A/D3010	
H_N	. NA	NA	NA	NA	0003	N		NA	NA	A/D	
H_R_0	NA	NA	NA	NA	0004	0000	3010	NA	NA	A/D3010	
H_R_N	NA	NA	NA	NA	0004	N		NA	NA	A/D	
	NA	NA	NA	NA				NA	NA	A/D	
P_0.H_0	0001	0000	0003	0000	0005	0000	3010	•	0	A3010	
H_G_0.H_R_0	0002	0000	0004	0000	0005	0001	3011	+	0	A3011	
H_0.P_0.H_G_0.H_R_0	0005	0000	0005	0001	0005	0002	3011	•	1	A3011	
H_0/P_0.H_G_0.H_R_0	0003	0000	0005	0002	0005	0003	3010	•	2	D3010	
Additional modules					0005					A/D	

F16.9



F1G.10